AMTECH
FastTest V

Amtech 2009 17th Edition

Hind-Smith Mansion

888 Wisemanville Crescent

Bollinger Farm

Buckinghamshire

MK99 8WW

12 Casablanca Grove

N/A

12 Casablanca Grove

Henley Hill

Cambridgeshire

CA88 3BS

1)All New Lighting and Power to Flat as per Distribution Board Schedule 2) All New Lighting and Power to Flat as per Distribution Board Schedule 3)All New Lighting and Power to Flat as per Distribution Board Schedule 4)All New Lighting and Power to Flat as per Distribution Board Schedule 5)All New Lighting and Power to Flat as per Distribution Board Schedule 6) All New Lighting and Power to Flat as per Distribution Board Schedule 7) All New Lighting and Power to Flat as per Distribution Board Schedule 8) All New Lighting and Power to Flat as per Distribution Board Schedule 9) All New Lighting and Power to Flat as per Distribution Board Schedule 10) All New Lighting and Power to Flat as per Distribution Board Schedule 11) All New Lighting and Power to Flat as per Distribution Board Schedule 12)All New Lighting and Power to Flat as per Distribution Board Schedule 13) All New Lighting and Power to Flat as per Distribution Board Schedule 14) All New Lighting and Power to Flat as per Distribution Board Schedule 15) All STOP

✓

✓

✓

2008

N/A

Albert Einstein

Albert Einstein

22/02/2006

1)All New Lighting and Power to Flat as per 2)All New Lighting and Power to Flat as per 3)All New

Derek Smith

Derek Smith

22/02/2006

1 Week

DSE Services

28 Avery Walk
Walnut Hill
Milton Keynes
Buckinghamshire

1)All New Lighting and Power to Flat as per Distribution Board Schedule 2) All New Lighting and Power to Flat as per Distribution Board Schedule 3)All New Lighting and Power to Flat as per Distribution Board Schedule 4)All New Lighting and Power to Flat as per Distribution Board
--See Additional Page--

01908 606123

MK5 4DS

N/A

1 2 3 5

2 2 2

AMTECH
FastTest V

✓	N/A	N/A	230	50	88 Fuse HRC	
✓	N/A	N/A	230	0.100	gG	
✓	6-Phase 12-Wire		LIM	N/A	100	80
				0.325		
N/A	Earth Rod	Rear of the garden		80	5419 Isolator	230
✓	6.35	Test Method 1 (3 wire)	ADS	4	3	100
Copper		Copper	16	✓	N/A	×	Copper	N/A
16	✓	In the cupboard			✓	N/A	25	N/A

		N/A	✓		✓
	✓	✓	✓		N/A
N/A			N/A		N/A
		✓	✓		✓
✓	✓	✓	✓		N/A
					✓
		N/A			N/A
		✓	✓		N/A
✓		✓	✓		✓
N/A		✓	✓		N/A
✓		✓	✓		✓
N/A			✓		N/A
		✓	✓		
✓		N/A	✓		

AMTECH

FastTest V

*																								✓			
	Cooker	F	A	A	1	6	4	5	60898 MCB	B	40	10	N/A	1.15	N/A	0.65	0.75	0.85	0.95	200+	200+	200+	200+	✓	0.97	N/A	N/A
2/TP	Shower	F	A	B	1	6	4	0.4	60898 MCB	B	32	10	N/A	1.44	N/A	0.65	0.75	0.85	0.95	200+	200+	200+	200+	✓	0.97	N/A	N/A
3/TP	Ring Main Down	F	A	C	10	2.5	1.5	0.4	60898 MCB	B	16	10	N/A	2.87	N/A	0.65	0.75	0.85	0.95	200+	200+	200+	200+	✓	0.97	N/A	N/A
4/TP	Ring Main Up	F	A	D	10	2.5	1.5	0.4	60898 MCB	B	20	10	N/A	2.30	N/A	0.65	0.75	0.85	0.95	200+	200+	200+	200+	✓	0.97	N/A	N/A
5/TP	Immersion Heater	F	A	E	1	2.5	1.5	0.4	60898 MCB	B	10	10	N/A	4.60	N/A	0.65	0.75	0.85	0.95	200+	200+	200+	200+	✓	0.97	N/A	N/A
6/TP	Lighting Circuit	F	A	F	5	1.5	1	0.4	60898 MCB	B	10	10	N/A	4.60	N/A	0.65	0.75	0.85	0.95	200+	200+	200+	200+	✓	0.97	N/A	N/A
7/TP	Lighting	F	A	G	5	1.5	1	0.4	60898 MCB	B	10	10	N/A	4.60	N/A	0.65	0.75	0.85	0.95	200+	200+	200+	200+	✓	0.97	N/A	N/A
8/TP	Cooker	F	A	100	5	1.5	1	0.4	60898 MCB	B	10	10	N/A	4.60	N/A	0.65	0.75	0.85	0.95	200+	200+	200+	200+	✓	0.97	N/A	N/A
9/TP	Lighting	F	A	101	5	1.5	1	0.4	60898 MCB	B	10	10	N/A	4.60	N/A	0.65	0.75	0.85	0.95	200+	200+	200+	200+	✓	0.97	N/A	N/A
10/TP	Sub Mains(Main House Power)	D	A	102	5	1.5	1	0.4	60898 MCB	B	10	10	N/A	4.60	N/A	0.65	0.75	0.85	0.95	200+	200+	200+	200+	✓	0.97	N/A	N/A
11/TP	Ring Main	F	A	103	5	1.5	1	0.4	60898 MCB	B	10	10	N/A	4.60	N/A	0.65	0.75	0.85	0.95	200+	200+	200+	200+	✓	0.97	N/A	N/A
12/TP	Swimming Pool Filter	F	A	A	2	4	2.5	0.4	60898 MCB	B	16	10	N/A	2.87	N/A	0.65	0.75	0.85	0.95	200+	200+	200+	200+	✓	0.97	N/A	N/A
13/TP	Swimming Pool Heater	F	A	B	1	2.5	1.5	0.4	60898 MCB	B	20	10	N/A	2.30	N/A	0.65	0.75	0.85	0.95	200+	200+	200+	200+	✓	0.97	N/A	N/A
14/TP	Shower	F	A	C	5	1.5	1	0.4	60898 MCB	B	10	10	N/A	4.60	N/A	0.65	0.75	0.85	0.95	200+	200+	200+	200+	✓	0.97	N/A	N/A
15/TP	Kitchen Sockets	F	A	D	5	1.5	1	0.4	60898 MCB	B	10	10	N/A	4.60	N/A	0.65	0.75	0.85	0.95	200+	200+	200+	200+	✓	0.97	N/A	N/A
16/TP	Lounge Sockets	F	A	E	5	1.5	1	0.4	60898 MCB	B	10	10	N/A	4.60	N/A	0.65	0.75	0.85	0.95	200+	200+	200+	200+	✓	0.97	N/A	N/A
17/TP	Study Sockets	F	A	F	5	1.5	1	0.4	60898 MCB	B	10	10	N/A	4.60	N/A	0.65	0.75	0.85	0.95	200+	200+	200+	200+	✓	0.97	N/A	N/A
18/TP	Dining Room Sockets	F	A	G	5	1.5	1	0.4	60898 MCB	B	10	10	N/A	4.60	N/A	0.65	0.75	0.85	0.95	200+	200+	200+	200+	✓	0.97	N/A	N/A
19/TP	Bathroom Sockets	F	A	100	5	1.5	1	0.4	60898 MCB	B	10	10	N/A	4.60	N/A	0.65	0.75	0.85	0.95	200+	200+	200+	200+	✓	0.97	N/A	N/A
20/TP	Bedroom 1 Sockets	F	A	101	5	1.5	1	0.4	60898 MCB	B	10	10	N/A	4.60	N/A	0.65	0.75	0.85	0.95	200+	200+	200+	200+	✓	0.97	N/A	N/A

In the cupboard

Main Power Supply

N/A

21/TP	Bedroom 2 Sockets	F	A	102	5	1.5	1	0.4	60898 MCB	B	10	10	N/A	4.60	N/A	0.65	0.75	0.85	0.95	200+	200+	200+	200+	✓	0.97	N/A	N/A
22/TP	Ensuite Sockets	F	A	103	5	1.5	1	0.4	60898 MCB	B	10	10	N/A	4.60	N/A	0.65	0.75	0.85	0.95	200+	200+	200+	200+	✓	0.97	N/A	N/A
23/TP	Attic Sockets	F	A	A	5	1.5	1	0.4	60898 MCB	B	10	10	N/A	4.60	N/A	0.65	0.75	0.85	0.95	200+	200+	200+	200+	✓	0.97	N/A	N/A
24/TP	Upstairs Lights	F	A	B	5	1.5	1	0.4	60898 MCB	B	10	10	N/A	4.60	N/A	0.65	0.75	0.85	0.95	200+	200+	200+	200+	✓	0.97	N/A	N/A
25/TP	Downstairs Lights	F	A	C	5	1.5	1	0.4	60898 MCB	B	10	10	N/A	4.60	N/A	0.65	0.75	0.85	0.95	200+	200+	200+	200+	✓	0.97	N/A	N/A

In the cupboard

Main Power Supply

N/A

1/TP	Immersion Heater		A	A	1	2.5	1.5	0.4	1361 Fuse HBC	2	30	33	N/A	1.15	0.35	0.35	N/A	N/A	555>	200+	200+	200+	200+	✓	0.1	N/A	N/A
2/TP	Sub Mains(Training Room 1)		B	B	1	16	10	5	1361 Fuse HBC	2	80	33	N/A	0.50	N/A	N/A	N/A	N/A	N/A	200+	200+	200+	200+	✓	N/A	N/A	N/A
3/TP	Lighting		A	C	2	2.5	2.5	0.4	60898 MCB	B	10	10	N/A	4.60	N/A	0.35	N/A	N/A	N/A	200+	200+	200+	200+	✓	3.5	N/A	N/A
4/TP	SPARE	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-
5/TP	Cooker		A	C	2	2.5	2.5	0.4	88 Fuse HRC	mG	6	80	N/A	8.52	N/A	0.35	0.65	N/A	555>	200+	200+	200+	200+	✓	N/A	N/A	N/A
6/TP	JHYT		A	C	2	2.5	2.5	0.4	60898 MCB	B	6	10	N/A	7.67	N/A	0.35	N/A	N/A	N/A	200+	200+	200+	200+	✓	N/A	N/A	N/A
7/TP	Ring Main		A	C	2	2.5	2.5	0.4	60898 MCB	B	6	10	N/A	7.67	N/A	0.35	N/A	N/A	555>	200+	200+	200+	200+	✓	N/A	N/A	N/A
8/TP	Shower		A	C	2	2.5	2.5	0.4	88 Fuse HRC	gG	32	80	N/A	1.04	N/A	0.35	N/A	N/A	555>	200+	200+	200+	200+	✓	N/A	N/A	N/A

Cupboard under the

Main House Power

0.25

1/L1	Cooker		A	A	9	2.5	1.5	0.4	1361 Fuse HBC	1	30	33	N/A	1.15	025	0.33	0.22	N/A	0.32	N/A	200+	200+	200+	✓	0.22	N/A	N/A
2/L1	JTT		A	A	9	2.5	1.5	0.4	60898 MCB	B	16	10	N/A	2.87	025	0.33	0.22	0.66	0.54	N/A	200+	200+	200+	✓	0.3	N/A	N/A
3/L1	GCN		A	A	2	2.5	1.5	0.4	60898 MCB	B	32	10	30	1.44	025	0.33	0.22	0.66	0.54	N/A	200+	200+	200+	✓	0.1	N/A	N/A
4/L1	Ring Main		A	C	2	2.5	2.5	0.4	1361 Fuse HBC	1	30	33	N/A	1.15	025	0.33	0.22	0.66	0.54	N/A	200+	200+	200+	✓	0.2	N/A	N/A
5/L1	Ring Main		A	C	2	2.5	2.5	0.4	60898 MCB	B	6	10	N/A	7.67	025	0.33	0.22	0.66	0.54	N/A	200+	200+	200+	✓	0.4	N/A	N/A
6/L1	Lighting		E	C	10	1.5	1	0.4	60898 MCB	B	10	10	N/A	4.60	025	0.33	0.22	0.66	0.54	N/A	200+	200+	200+	✓	0.6	N/A	N/A
7/L1	Cooker		A	A	1	2.5	1	0.2	1361 Fuse HBC	1	20	33	N/A	1.49	025	0.33	0.22	0.66	0.54	N/A	200+	200+	200+	✓	0.7	N/A	N/A
8/L1	Ring Main	F	D	C	1	10	6	5	1361 Fuse HBC	2	20	33	N/A	2.80	025	0.33	0.22	0.66	0.54	N/A	200+	200+	200+	✓	0.8	N/A	N/A